

Menu

HISTORY FILE MAP for year 2004

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

4m 1024bps real-time data lost due to re-sweeping of transmitter at DSS54. DR M102756 refers.

12m 512bps real-time data lost at beginning of DSS24 track due to loading of incorrect station predicts. DR G104835 refers.

